3DS - Training 1

Training	Introductory
Level	1
Туре	ON-MACHINE
Time Estimate	50 min
Prerequisites	None
Access Gained	Unsupervised Equipment Access
User Level	BASIC USER
Objectives	 Calibrate the C-Track. Scan an object. Clean up a scan in VXscan and VXmodel. Export scan to Solidworks. Verify a design in VXinspect.
Checklist/Document	
Models	CAD files of the object scanned in the training session: • Fusion 360 File: • STEP File:



⚠ Google Apps Sign-in Required

You must sign-in to your uAlberta Google apps account to download these files.