DP - Training 1

Training	Introductory
Level	1
Туре	ON-MACHINE
Time Estimate	50 mins
Prerequisites	None
Access Gained	Unsupervised Equipment Access
User Level	BASIC USER
Objectives	 Setup a workpiece and sacrificial backing piece Determine correct RPM based on material and drill size Installing a drill bit Drill a hole into the workpiece using the peck drilling technique
Checklist/Document	
Models	N/A

Google Apps Sign-in Required

You must sign-in to your uAlberta Google apps account to download these files.