

# Support Removal Tanks

About	The three support removal tanks are used to dissolve the soluble support used in Stratasys J750, Fortus 450mc and F120 prints.
Category	3D Printing
Location	Back Room

## Model Specifics

Properties	Status	Materials	About
Rinse Tank (SCA1200)	AVAILABLE	N/A	A small heated bath reserved for rinsing parts.
Polyjet Support Removal Tank (CSIIIP)	AVAILABLE	<ul style="list-style-type: none"><li>706B</li></ul>	A large cold bath reserved for the 706 B material from the Stratasys J750.
FDM Support Removal Tank (SCA3600)	AVAILABLE	<ul style="list-style-type: none"><li>SR-30</li><li>SR-100</li><li>SR-110</li></ul>	A large heated bath reserved for the support materials from the Stratasys FDM printers.



Left to right: Polyjet Support Removal Tank (CSIIIP), FDM Support Removal Tank (SCA3600), and Rinse Tank (SCA1200)

## Standard Operating Procedure



### Google Apps Sign-in Required

You must login to your [uAlberta Google apps](#) account to access these files.

## Training



The Garage does not offer training on the Support Removal Tank. Request access to the tanks from Garage staff.

## Training

---

No content found.

---

# Documentation



### Google Apps Sign-in Required

You must login to your [uAlberta Google apps](#) account to access these files.

<b>Safety Data Sheets</b>	
<b>Hazard Assessments</b>	
<b>Application Resources</b>	
<b>Manufacturer's Manuals</b>	