CNC Mills - 2B Basics

Training	CNC Mill Basics
Level	2B
Туре	ON-MACHINE ON-MACHINE
Time Estimate	2 hrs.
Prerequisites	CNC Mills - 1B Intro. and CNC Mills - 2A Basics Plan
Access Gained	 CNC mill access with PathPilot generated toolpaths and tools that are installed in the machine. CNC Mills - 3B Advanced NOTE: The first independent use will be a shadowed session and test your knowledge on the CNC mill use. We will test if you can complete the CNCM 2B checklist items independently.
User Level	BASIC USER
Objectives	 Setup workholding and work coordinate systems (WCS) in the CNC mill. Create facing, profiling, pocketing operations in PathPilot. Machine a multi-setup part.
Checklist /Document	
Models	N/A



You must sign-in to your uAlberta Google apps account to download these files.